

99063034074000, 99063034074000

Request a review of the increased risk from incidents

Heruntergeladen am 26.06.2025

<https://fimportal.de/xzufi-services/213524986/L100038>

Modul	Sachverhalt
Leistungsschlüssel	99063034074000, 99063034074000
Leistungsbezeichnung I	Request a review of the increased risk from incidents
Leistungsbezeichnung II	
Typisierung	2/3 - Bund: Regelung (2 oder 3), Land/Kommune: Vollzug
Quellredaktion	Thüringen
Freigabestatus Katalog	unbestimmter Freigabestatus
Freigabestatus Bibliothek	fachlich freigegeben (silber)
Begriffe im Kontext	
Leistungstyp	Leistungsobjekt mit Verrichtung
Leistungsgruppierung	Immissionsschutz (063)
Verrichtungskennung	Überprüfung (074)
SDG-Informationsbereich	Gesundheits- und Sicherheitsvorschriften im Zusammenhang mit verschiedenen Arten von Tätigkeiten, einschließlich der Risikovermeidung, Information und Ausbildung

Modul	Sachverhalt
Lagen Portalverbund	Anlagenbetrieb und -prüfung (2120100)
Einheitlicher Ansprechpartner	Nein
Fachlich freigegeben am	28.11.2024
Fachlich freigegeben durch	Thuringian Ministry for the Environment, Energy and Nature Conservation (TMUEN)
Handlungsgrundlage	https://www.gesetze-im-internet.de/bimschv_12_2000/_15.html https://www.gesetze-im-internet.de/bimschv_12_2000/_7.html https://www.gesetze-im-internet.de/bimschv_12_2000/_15.html https://www.gesetze-im-internet.de/bimschv_12_2000/_7.html
Teaser	For neighboring operating areas, the authority checks whether domino effects exist.
Volltext	<p>In accordance with the Major Accidents Ordinance, the competent authority is obliged to determine for the operators of establishments which establishments or groups of establishments, due to their geographical location, their distance from each other and the hazardous substances present in their installations, may have an increased probability of major accidents or which may have more serious consequences (domino effect). For the assessment, the authority uses in particular</p> <ul style="list-style-type: none"> • the information provided by the operator in the notification and in the safety report, • the information provided by the operator following a request for additional information from the competent authority, and • the information obtained by the competent authority through monitoring measures. <p>The information to be reported by the operator also includes circumstances in the immediate vicinity of the establishment which could trigger an incident or exacerbate its consequences, e.g. details of neighboring establishments, other establishments not</p>

Modul

Sachverhalt

covered by the Major Accidents Ordinance, and areas and developments from which an incident could emanate or where the probability of an incident occurring could increase or the consequences of an incident and domino effects could be exacerbated. If the authority also has additional information, it must make this available to the operator without delay, insofar as this is necessary for cooperation between the operators.

Erforderliche Unterlagen

Voraussetzungen

Kosten

Fees are charged for the assessment notice, which are based on the respective fee regulations of the federal states.

Verfahrensablauf

The procedure for determining a domino effect is initiated by the competent authority. The assessment is based on

- the information provided by the operator in the notification and in the safety report
- the information provided by the operator following a request for additional information from the competent authority, and
- the information obtained by the competent authority through surveillance measures.

If the conditions for a domino effect are met, the competent authority shall issue a declaratory decision to the operators concerned.

Bearbeitungsdauer

Frist

weiterführende Informationen

Hinweise

Rechtsbehelf

An appeal can be lodged against a declaratory decision.

Kurztext

- Increased risk due to incidents (domino effect) Review

Modul	Sachverhalt
	<ul style="list-style-type: none"> • For the assessment, the authority uses in particular the information provided by the operator in the notification and in the safety report, the information provided by the operator following a request for additional information from the competent authority, and the information obtained by the competent authority through monitoring measures.
Ansprechpunkt	Please contact the immission control authority of your district or city or the Thuringian State Office for the Environment, Mining and Nature Conservation.
Zuständige Stelle	Immission control authority or Thuringian State Office for the Environment, Mining and Nature Conservation
Formulare	
Ursprungsportal	Request a review of the increased risk from incidents, Überprüfung der erhöhten Gefahr durch Störfälle beantragen